

Rev.
19/04/2017

Materials Characterization Facility

Mechanical Characterization lab rules

Manager: Luca Ceseracciu luca.ceseracciu@iit.it, Ext. 241

- All the tools on the working benches and inside the drawers and toolbox are necessary for sample preparation and instrument operation; they cannot be removed from the laboratory.
- The working benches can be used only for sample preparation in dry conditions; no solvents are allowed in the laboratory, excepted minor quantities of water and ethanol for sample rinsing.
- Report any malfunction or issue to the lab manager.
- The instruments are sensitive to vibrations: avoid any unnecessary noise.
- In the case of out-of-hours access, a second person must be in the building within reach and the lab door must be kept open
- OXYGEN SENSORS: in case of beeping sensor, leave the Lab immediately and alert the Lab manager
- Save your data files only to your personal folder. In order to take your files with you, the preferred method is the direct transfer to the shared public folder: <\\iit.local\public\Nanobiotech\MCF>